

## DEPARTMENT OF DISABILITIES, AGING AND INDEPENDENT LIVING

Division of Licensing and Protection 103 South Main Street, Ladd Hall Waterbury, VT 05671-2306 http://www.dail.vermont.gov Voice/TTY (802) 871-3317 To Report Adult Abuse: (800) 564-1612 Fax (802) 871-3318

April 2, 2014

Ms. Wanda Waugh, Administrator Canterbury Inn 46 Cherry Street Saint Johnsbury, VT 05819-2290

Provider # 0119

Dear Ms. Waugh:

Enclosed is a copy of your acceptable plans of correction for the unannounced onsite survey follow up conducted on **January 30**, **2014**. Please post this document in a prominent place in your facility.

We may follow up to verify that substantial compliance has been achieved and maintained. If we find that your facility has failed to achieve or maintain substantial compliance, remedies may be imposed.

Sincerely,

Pamela M. Cota, RN Licensing Chief

PC:ne

Enclosure

PRINTED: 02/10/2014 FORM APPROVED

Division of Licensing and Protection STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA FEB 2 1 14 (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING: \_ Licensing and Protection B. WING 0119 01/30/2014 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **46 CHERRY STREET CANTERBURY INN** SAINT JOHNSBURY, VT 05819 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5)(EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PREFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) {R100} Initial Comments: {R100} An unannounced onsite survey follow up was conducted by the Division of Licensing and Protection on 1/30/14. The following regulatory deficiency was identified. R291 IX. PHYSICAL PLANT R291 SS=F 9.6 Plumbing 9.6.d Hot water temperatures shall not exceed 120 degrees Fahrenheit in resident areas. This REQUIREMENT is not met as evidenced by: Based on observation and staff interview, the home failed to assure that water temperatures in resident areas were not over 120 Degrees F. Findings include: Per observation on 1/30/14 at 1:50 PM, the hot water in the upstairs resident shared bathroom sink near the elevator was at 129 Degrees F. The other shared bathroom and one private resident bathroom were checked also, with similar readings between 128-130 degrees F. recorded. Readings were then taken in the sinks in the downstairs shared resident bathroom and the laundry room sometimes used by more POC accepted 3/27/14 Karenlampor independent residents and the hot water was between 134 Deg. F and 136 Deg. F. at 1:55 PM. Per interview with the person in charge of maintenance, the residents had complained of cooler hot water temperatures while bathing, and the mixing valve had been adjusted toward hotter temperatures. They had recently installed a commercial clothes washing machine that used a lot of hot water when running, and that this was causing some problems with bath water Division of Licensing and Protection LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

974712

TITLE

(X6) DATE ·

If continuation sheet 1 of 2

Division of Licensing and Protection STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: \_ B. WING 0119 01/30/2014 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **46 CHERRY STREET CANTERBURY INN** SAINT JOHNSBURY, VT 05819 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE CROSS-REFERENCED TO THE APPROPRIATE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG **DEFICIENCY**) R291 Continued From page 1 R291 temperatures being too cool at times. At 2:00 PM, the head of maintenance and this surveyor concurrently checked the water temperature in the laundry room sink and it was reading approximately 134 Degrees F. The mixing valve was then adjusted, and within a couple of minutes was reading below 120 D. F. in all of the resident areas measured. At 2:05 PM on 1/30/14, the head of maintenance confirmed that the water temperatures were set above the regulatory limit of 120 Degrees F., and were above this temperature in resident areas.

Division of Licensing and Protection

STATE FORM

9Z4Z12

## Plan of Correction

R291: On the afternoon of 01/30/2014 the State surveyor found that the hot water temp in one of the bathrooms was 129 degrees F. Upon further inspection, the surveyor found several bathrooms with a hot water temperature range of 128-136 degrees F. maintenance man was notified and he subsequently adjusted the mixing valve while the surveyor was still on site. Within a short period of time all of the hot water temps were at or below 120 degrees F.

Starting on 01/30/2014, the maintenance man has been checking 3 faucets weekly in random parts of the building. The readings have ranged from 110-118 degrees F. Apparently the hot water booster heater in the kitchen—and the commercial washer in the basement laundry area pull the hot water away from specific bathrooms, hence cool water temps for bathing. The nursing attendants have been working with dietary and housekeeping to coordinate bath times with laundry and dishwasher use. So far, the complaints about "cold water" have been far less and our water temps have remained in range.

Our maintenance man has checked our water temps every month for several years now. Please find the enclosed copy of the past three years. He only turned the temperature up when he started to get complaints of cold water for baths.

Maintenance will continue to monitor water temps as he has previously done, but reports of "cold water" will be directed to Wanda Waugh RN as well as to maintenance. Water temperature adjustments will only be done when both parties agree to the solution. If the mixing valve needs to be adjusted, the water temps will be taken 3 times the first day, twice the second day and once the third day. They will continue to be checked weekly for three consecutive weeks and then back to once a month thereafter.

Tranda Trangle RN

02/18/14

POC accepted K Campon RN